


JA33 Installation Kit INST-JA33

Contents:

| JAC P/N | DESCRIPTION | QTY | |
|---------------|--------------------|-----|--|
| CON-3420-0015 | CONNECTOR ASSEMBLY | 1 | |
| CON-5500-0375 | TAG RING | 1 | |
| WIR-HTSK-0750 | HEATSHRINK TUBING | 1 | |

| Standard D-Sub Crimp Tool Chart | | | | |
|---------------------------------|--------------------|-------------|--------------------------|--|
| TOOL TYPE | HAND CRIMPING TOOL | POSITIONER | INSERTION/EXTRACTOR TOOL | |
| POSITRONIC | 9507-0-0-0 | 9502-5-0-0 | 4711-2-0-0 | |
| DANIELS | AFM 8 | K13-1 | 91067-2 | |
| MIL-SPEC | M22520/2-01 | M22520/2-08 | M81969/1-02 | |




15 Pin Connector Assembly

Assembly Notes

- Slide Heat-shrink tubing (M12) and Tag Ring (M9) over wiring harness.
 String outer inselect of chiefded conductors approximately 3" for the conducto
- 2. Strip outer jacket of shielded conductors approximately 3" from connector end.
- 3. Extract conductors through shield at the 3" mark.
- 4. Flatten and face shields pigtails away from connector end.
- 5. Strip and crimp Pins (M11) to wires.
- 6. Insert Pins (M11) into Connector (M10).
- 7. Insert Spring (M4) into Body (M1).
- 8. Place Lock-arm (M3) over Connector (M10) and secure to Body (M1) with Screws (M8).
- Place Clamp (M5) around wire harness and secure with screws (M6).
- Place Clamp (M5) partially into Body (M1) and secure with Hood (M2) and Screws (M7).
- 11. Position Tag-Ring body (M9) on the connector side of the pigtails and Tag Ring nut after the pigtails.
- 12. Distribute pigtails uniformly into the Tag Ring (M9) slots. If necessary, double back pig-tails to achieve uniform shield thickness between adjacent slots.
- 13. Tighten Tag-Ring nut securely. Leave pigtails approximately 1" long to facilitate repairs.
- 14. Flatten pigtails against the Tag Ring body and tie behind the nut.
- 15. Slide Heat-Shrink (M12) over the Tag Ring and shrink in place.

| ITEM NO. | DESCRIPTION | QTY* |
|---------------------------|-------------------|------|
| M1 | BODY | 1 |
| M2 | HOOD | 1 |
| M3 | LOCKARM | 1 |
| M4 | SPRING | 1 |
| M5 | CLAMP | 2 |
| M6 | CLAMP SCREW | 2 |
| M7 | FLATHEAD SCREW | 2 |
| M8 | PANHEAD SCREW | 2 |
| M9 | TAG RING | 1 |
| M10 | CONNECTOR | 1 |
| M11 | PINS | 15 |
| M12 *Quantities Per Cable | HEATSHRINK TUBING | 2" |



Tag Ring Assembly



